

Accident in Sanborn Yard.

Sanborn Enterprise: The Branch train backed through a switch just before it reached its stub at the east end of the depot last Saturday night and was partially derailed close to the main track. At the same time a stock train started to pull out from the depot on the main line and came in contact with the smoker of the Branch train tipping it at a sharp angle, though not completely turning it on its side. Both trains were moving slowly, otherwise the accident might have been more serious. Two men, occupants of the smoker, were slightly hurt and their injuries were dressed by Dr. Lang, resident N. P. surgeon. Traffic was held up at this point for two or three hours while the tracks were being cleared. No. 8 was held at Eckelson and passed 135 at this station.